

July 2019

Dear Customer:

Nipron Co., Ltd.

### Notice of Discontinuation

Thank you very much for your continued patronage.

At this time, we regret to inform you that the product models listed in the table below will be discontinued for the reasons listed below.

With warm regards,

#### ◆ Models to be discontinued

Model number	End of sales	Last order availability	Recommended replacement model*	Notes
PCSA-300P-X2S	December, 2020	December, 2019	PCSA-370P-X2S	With output harness
PCSA-300P-X2V	December, 2020	December, 2019		
PCSA-470P-E2J1	December, 2020	December, 2019	ePCSA-500P-X2S ePCSA-650P-E2S	Output harness sold separately
PCSA-470P-E2S	December, 2020	December, 2019		
PCSA-470P-X2S	December, 2020	December, 2019		
PC1U-210P-X2S	December, 2020	November, 2019	HPC1U-400P-X2S	Output harness sold separately
PC1U-210P-X2S-02	December, 2020	November, 2019		
PCTF-220P-X2S	June, 2020	December, 2019	PC12U-200P-X2SV-02	With output harness
PCTF-220P-X2S-02	June, 2020	December, 2019		

\* These models may not be 100% compatible. Please check the product specifications carefully.

#### ◆ Reasons for discontinuation

The electronic parts needed to make these products are steadily going out of production. In addition, the listed models have been on the market for over 10 years and the volume of sales has dropped to insignificant levels, which makes their continued production difficult. For these reasons we have decided to discontinue production.

#### ◆ Accepting Final Orders

We have set the end of sales date as above, but please understand that limited inventory could still prevent us from delivering your order. So, to ensure that we will be able to answer your request, we have set a deadline for final orders well in advance of the planned end of production. Please be sure to place your order by the dates listed above for the models being discontinued.

If you have any questions, please don't hesitate to contact one of our sales representatives.